



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

NMOCd

JUN 21 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6.19.19 Operator Hilco Energy API #30-0 39-20712
Property Name San Juan 29.5 lot Well No. 68 Location: Unit Section 18 Township 29 Range 5
Well Status (Shut-In or Producing) Initial PSI: Tubing 104 Intermediate 100 Casing 107 Bradenhead 100

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	16	45	108	0	104
10 min	2	10	107	0	104
15 min	0.9	2	106	0	104
20 min	0	1	106	0	103
25 min	0	0.8	105	0	103
30 min	0	0	105	0	103

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	☒	☒
Surges	☐	☐
Down to Nothing	☐	☐
Nothing	☐	☐
Gas	☒	☒
Gas & Water	☐	☐
Water	☐	☐

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 2

INTERMEDIATE 2

REMARKS:

BH = fluid blow when opened to light for full 30 min
Test - int dropping with bradenhead - Int. had blow when
opened - to medium - for rest of 30 min test

By Kyle D Smith

Witness Monica Cuchling

(Position)

E-mail address gas analysis all things