



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://emnrd.state.nm.us/ocd/District III/3distric.htm>

**BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 6/5/19 Operator ENDURING RESOURCES IV LLC API #30-039-25453

Property Name RINCON UNIT Well No. 138E Location: Unit F Section 25 Township 27N Range 07W

Well Status (Shut-In or Producing) Initial PSI: Tubing 26 Intermediate N/A Casing 54 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME	Ø		55		
5 min	Ø		55		
10 min	Ø		55		
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing ✓	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø INTERMEDIATE N/A

REMARKS:

By John Dockter

Witness \_\_\_\_\_

HSE Tech  
(Position)

E-mail address JDockter@EnduringResources.com

NMOC  
JUN 12 2019  
DISTRICT III

6/11/19