



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

NMOCOD

JUL 11 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7.10.19 Operator Enduring Res API #30-0 39-06868
Property Name Tricon let Well No. 149 Location: Unit Section 30 Township 27 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 33 Intermediate 43 Casing 51 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	43	51	1	48
10 min	0	43	48	0	47
15 min	0	43	48	0	50
20 min				0	51
25 min				0	53
30 min				0	54

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		/
Surges		/
Down to Nothing	-	
Nothing		
Gas	/	/
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 5

REMARKS:

Not blown down prior to testing
BH - light blow thru needle valve - 1 minute -
30 seconds - 1/2" valve - to clear - light blow
through needle valve after 5 min pressure -

By John Dockter

Witness Monica Quehling

USE Tech
(Position)

E-mail address JDockter@EnduringReserves.com Gas analyses Int production tubing well bore schematic
Int - Hard blow when opened - surging at 3.5 minutes
through OW & a light blow at 10 min. 15-20-25-30 -