



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

NMOC

JUL 11 2019

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DISTRICT III

Date of Test 7-10-19 Operator Enduring Res API #30-0 39-07081

Property Name R. Conduit Well No. 78 Location: Unit 14 Section 14 Township 27 Range 2

Well Status (Shut-In or Producing) Initial PSI: Tubing 60 Intermediate 672 Casing 66 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME	0	672	66	127	64
5 min	0	672	66	26	63
10 min	0	672	66	6	63
15 min	0	672	66	2	61
20 min				1	60
25 min				1	57
30 min					

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow	<u>✓</u>	<u>✓</u>
Surges		
Down to Nothing		
Nothing	<u>✓</u>	
Gas		<u>✓</u>
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 5

REMARKS:

This well has not been blown down. It nothing
when opened. It nothing when opened. Int. had blow when
opened. blew full 30 min test.

By John Dackter

Witness Monica Kuchling

HSE Tech
(Position)

Gas analysis. Well bore schematic
- tubing - Prod casing - Int.

E-mail address JDackter@EnduringResources.com