



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emmr.state.nm.us/ocd/District III/3district.htm](http://emmr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/17/19 Operator Reddy R Production API #30-0 39-21455

Property Name Chacon Jicarilla PL Well No. 11 Location: Unit 6 Section 16 Township 23 Range 3

Well Status (Shut-In or Producing) Initial PSI: Tubing 59 Intermediate NA Casing 59 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>59</u>		
10 min	<u>0</u>		<u>59</u>		
15 min	<u>0</u>		<u>59</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>1</u>
Nothing	<u>1</u>
Gas	<u>1</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS: Puff of gas when first opened. Nothing after
5 min. shut in.

By Jay J
Lease Manager
(Position)

Witness _____

E-mail address htixier@crowquest.com

NMOCD
JUN 05 2019
DISTRICT III