



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 6/10/19 Operator ENDURING RESOURCES IV LLC API #30-039-21971

Property Name RINCON UNIT Well No. 108A Location: Unit I Section 19 Township 27N Range 06W

Well Status (Shut-In or Producing) Initial PSI: Tubing 63 Intermediate N/A Casing 76 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM		
	BH	Bradenhead Int	Csg	Int	Csg	
5 min	Ø		73			
10 min	Ø		69			
15 min	Ø		65			
20 min						
25 min						
30 min						

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	✓	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø

INTERMEDIATE N/A

REMARKS:

opened to sales during test

By John Dockter

Witness \_\_\_\_\_

HSE Tech  
(Position)

E-mail address JDockter@EnduringResources.com

NMOCD  
JUN 19 2019  
DISTRICT III

6/18/19