

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

	copy to above address)		
Date of Test 6/24/19 Operator_ENDURING	RESOURCES IV LLCAPI #3	0-039-22311	
Property Name_RINCON UNIT_Well No021A_Loc			
Well Status(Shut-In or Producing) initial PSI: Tub	ing $98$ Intermediate $NA$	Casing 6 Brader	head Ø
OPEN BRADENHEAD AND INTERMEDIATE TO	O ATMOSPHERE INDIVIDU	JALLY FOR 15 MINU	TES EACH
PRESSURE  Testing Bradenhead INTERM  BH In Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE		
TIME S 96	Steady Flow		
10 min 96	Surges		
15 min 96	Down to Nothing		
20 min_	Nothing		
25 min	Gas		
30 min_	Gas & Water		
	Water		
If bradenhead flowed water, check all of the descriptions that apply below:			
CLEAR FRESH SALTY	SULFURBLACK		
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE 1/14			
REMARKS:			
By John Darkter W	itness		
HSE Tech			
E-mail address Jock to Endury Ros		NMOGD	
500000000000000000000000000000000000000	Com	JUL 00 2019	10/19
	L	DISTRICT III	7/9/19