

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6/27/19 Operator_ENDURING RESOURCES IV LLC_API #30-039-24495	
Property NameRINCON UNIT_Well No243_Location: Unit_K_ Section_27_Township_27N_Range06W_	
Well Status(Shut-In or Producing) Initial PSI: Tubing 33 Intermediate MA Casing 73 Bradenhead	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg TIME 5 min 73 10 min 72 20 min 72 25 min 30 min 30 min 73	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE Steady Flow Surges Down to Nothing Nothing Gas Gas & Water Water
If bradenhead flowed water, check all of the descriptions that apply below: CLEAR FRESH SALTY SULFUR BLACK 5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE REMARKS:	
By John Dockter Witness	