

## NEW MEXICO ENERGY, MINIERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test_5/6/19 Operator_ENDURING RESOURCES IV LLC_API #30-039-24689	
Property Name_RINCON UNIT_Well No278 _Location: Unit _H_Section_14_Township_27N_Range07W_	
Well Status(Shut-In or Producing) Initial PSI: Tubing 31 Intermediate M/A Casing 58 Bradenhead	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min 58	Steady Flow
10 min 58	Surges
15 min 8 58	Down to Nothing
20 min 9 58	Nothing
25 min 8 58	Gas
30 min 0   58	Gas & Water
Water  If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD OF INTERMEDIATE	
REMARKS: N/A	
By John Dockter Witness_	
HSE Tech (Position)	
E-mail address Docustura Encluding Resources. Com  MAY 18 200	
	19
DISTRICT III	