



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/15/19 Operator Roddy Production API #30-0 43-20431
Property Name Chacon Jic. Ap. D Well No. 108 Location: Unit G Section 26 Township 23 Range 3
Well Status (Shut-In or Producing) Initial PSI: Tubing 65 Intermediate NA Casing 78 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>78</u>		
10 min	<u>0</u>		<u>78</u>		
15 min	<u>0</u>		<u>78</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing <u>1</u>	
Nothing	
Gas <u>1</u>	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

Bradenhead Blew for about 5 seconds then down to nothing.
After 5min shut in had a little pressure but not enough to
make 1 psi on gauge.

By Tony Tixier
Lease Manager
(Position)

Witness _____

E-mail address ttixier@crowquest.com

NMOC
JUN 05 2019
DISTRICT III