

**NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

**BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 7/16/2019 Operator Hilcorp Energy Company API # 3003922414  
Property Name JICARILLA K Well No. 15E Location: Unit A Section 01 Township 025N Range 005W  
Well Status Flowing Initial PSI: Tubing 58 Intermediate          Casing 60 Bradenhead 32

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE					FLOW CHARACTERISTICS	
	BRADENHEAD			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
5 min	0		69			Steady Flow	Y
10 min	0		73			Surges	
15 min	0		77			Down to Nothing	
20 min	0		79			Nothing	
25 min	0		82			Gas	Y
30 min	0		84			Gas & Water	
						Water	

If Bradenhead flowed water, check all of the descriptions that apply below:

CLEAR          FRESH          SALTY          SULFUR          BLACK         

If Intermediate flowed water, check all of the descriptions that apply below:

CLEAR          FRESH          SALTY          SULFUR          BLACK         

5 MINUTE SHUT-IN PRESSURE Bradenhead 1.6 Intermediate         

REMARKS:

Test submitted 7/2/2019 for this well was incorrect (data entered was for the Jicarilla K 15). This is the correct information for this well. After 2 min light flow from BH.; 20% or more change in BH psi since last test. Gas samples taken

Tested By Brandon Noble Witness