

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

AUG 0 5 201'

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DISTRICT 111

Date of Test 8/5/2019 Operator Hilcorp Energy API #30-039-23650	
Property Name Caryon Largo Unit Well No. 308 Location: Unit 6 Section 5 Township 24 Range 6	
Well Status (Shut-In) or Producing) Initial PSI: Tubing NA Intermediate NA Casing 2.4 Bradenhead D	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min D -2.4	Steady Flow
10 min 0 -2.6	Surges
15 min 0 -2.6	Down to Nothing
20 min	Nothing
25 min	Gas
30 min_	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY	SULFURBLACK
5 MINUTE SHUT-IN PRESSURE BRADENHEAD D INTERMEDIATE NA	
Casing on a vacuum, no pressure on BH	
By Witness Witness (Position)	
E mail address	