



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

NMOCOD

JUL 15 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-15-19 Operator Red Willow Cr. API #30-0 39-31020
Property Name McClute 23D Well No. 2H Location: Unit I Section 9 Township 32 Range 4
Well Status (Shut-In or Producing) Initial PSI: Tubing 24 Intermediate 11A Casing 26 Bradenhead 58

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	0		25			Steady Flow	
10 min	0		25			Surges	
15 min	0		25			Down to Nothing	
20 min	0		25			Nothing	
25 min	0		25			Gas	/
30 min	0		25			Gas & Water	
						Water	/

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD

0

INTERMEDIATE

REMARKS:

Water flow (milky) for 30 seconds to 2 minutes
to clear at 3 min 30 seconds - Gallon of liquid. Whipped
at 5 min - 10 - 15 - 20 - 25 to clear - 30 clear

By Robert Munn

Witness Nomica Kuehling

(Position)

E-mail address _____

Puff when opened after 5 min
Shut in -
Water sample taken