

Inspection # IMPK 197041264



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emrmd.state.nm.us/ocd/District/III/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-9-19 Operator BPX API #30-0 4524948

Property Name BCU Well No. 226E Location: Unit C Section 18 Township 28N Range 12W

Well Status (Shut-In or Producing) Initial PSI: Tubing 18 Intermediate N/A Casing 38 Bradenhead 123

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	Ø		56.5			
10 min	Ø		57.6			
15 min	Ø		58.4			
20 min	Ø		59.1			
25 min	Ø		59.7			
30 min	Ø		60.2			
5 min shut-in	2.4		60.6			

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>Vapor</u>	
Surges	
Down to Nothing <u>3 min 55 sec</u>	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

JUL 11 2019

DISTRICT III

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 2.4 INTERMEDIATE N/A

REMARKS: No blowdown due to sampling. Samples BH-7010, T 7014, & C-77064.
Whisper @ start of test 3 min 55 sec Vapor after. Casing valve closed.

By Eugenia Hamilton
Technician
(Position)

Witness _____

E-mail address Eugenia.H@psosinc.biz