

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD **AZTEC NM 87410** (505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

NMOCD

JUL 7 6 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)
Date of Test 7.25.19 Operator Con One guapa PI #30-0 45-32335 Property Name Montoy a Well No. R Location: Unit B Section 35 Township 32 Range 13
Property Name Wortbya Well No. R Location: Unit Section 35 Township 32 Range 13
Well Status (Shut-In or Producing) Initial PSI: Tubing 45 Intermediate // Casing 51 Bradenhead 75
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
PRESSURE FLOW CHARACTERISTICS Testing Bradenhead INTERM BRADENHEAD INTERMEDIATE BH Int Csg Int Csg
TIME 5 min Steady Flow
10 min 0 53 Surges
15 min Down to Nothing
20 min O 54 Nothing
25 min 0 54 Gas
30 min 0 54 Gas & Water
Water
If bradenhead flowed water, check all of the descriptions that apply below:
CLEAR FRESH SALTY SULFUR BLACK
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE
REMARKS: Hard blow when opened to Mediumat 2 Deconds.
light blow at 5-10-15-20-25-30-vapors-
By Dacofea Witness Would Culling
(Position) Daniel Rios
E-mail address