



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-5178 FAX: (505) 334-5170
<http://emrur.state.nm.us/ocd/District183/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-4-19 Operator Dominion Prod API #30-0 31-2053

Property Name SH Well No. 14 Location: Unit E Section 12 Township 17 Range 9

Well Status (Shut-In or Producing) Initial PSI: Tubing 312 Intermediate Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>0</u>		
10 min	<u>0</u>		<u>0</u>		
15 min	<u>0</u>		<u>0</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<input checked="" type="checkbox"/>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: nothing when opened Bth, nothing after
5 min shut in

By [Signature]
(Position)

Witness

E-mail address

NMOCO
AUG 19 2019
DISTRICT III