

## NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test	7-30-19	Operator	Logos Operating,	LLC A	API # 300	3906291
Property Name	(Well Name a	and Number)	Location: Unit L			1
Pressure (Shut-in or Producing) Tubing 109 Intermediate N/A Casing 110 Bradenhead 70						
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
Time 5 minutes 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes 5 minute SI	Blowdown Monitor  27 1/1  21 1/0  18 1/0  12 1/0  7 109  6 109  45 109	Intermediate Monitor	Intermediate Intermediate Casing Blowdown Monitor  Criptions that apply below	Steady Flow Surges Down to Nothing No Flow Gas Gas and Water Water	Flowed	Intermediate Flowed
Clear         Fresh         Salty         Sulfur         Black           5 Minute Shut-in         Bradenhead         45         Intermediate         N/A						
REMARKS:						
Need API Number and unit letter/quarter/quarter on Sign						
By Eugene Burbonde Witness Wit						