

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

(submit 1 copy to above address)	
Date of Test 7/17/19 Operator_EN	DURING RESOURCES IV LLCAPI #30-039-06780
Property Name_RINCON UNIT_Well No. 0	72 Location: Unit P Section 33 Township 27N Range 07W
Well Status(Shut-In or Producing) Initial PS	SI: Tubing 3 Intermediate N/A Casing 1 Bradenhead
OPEN BRADENHEAD AND INTERMEDL	ATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
PRESSURE Testing Bradenhead INTERM BH Int Csg In Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
$\begin{array}{c c} \text{TIME} \\ 5 \text{ min} \\ \hline \\ 10 \text{ min} \\ \hline \\ \hline \\ \hline \\ \\ \hline \\ \hline \\ \hline \\ \\ \hline \\ \hline \\ \\ \hline \hline \\ \hline \\ \hline \\ \hline \\ \hline $	Surges
15 min 2 1	
20 min	Nothing DISTRICT
25 min	Gas
30 min	Gas & Water Water
If bradenhead flowed water, check all of the descr	and the second
CLEAR FRESH SALTY	SULFURBLACK
5 MINUTE SHUT-IN PRESSURE BRADI	enhead // Intermediate N/A
REMARKS:	
TOUL	
By John Docktor HSE Tech	Witness

DD ( DENILE ( D TECT DEDODT

(Position) E-mail address JDuckter Enduring Resources. com

129/19

11