

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 7-18-19 Operator: **Enervest Operating, LLC** API # 30-039-22301

Property Name: Jicarilla B Well No. 3E Location: Unit I Section: 15 Township: 26N Range: 5W

Well Status (Shut-In or **Producing**) Initial PSI: Tubing 101 Intermediate Casing 105 Braden head 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		105		
10 min	0		105		
15 min	0		105		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE	BRADENHEAD	0	INTERMEDIATE
----------------------------------	------------	---	--------------

REMARKS:

No Blow _____

By Rodale Curley

Witness _____

Lease Operator _____
(Position)

E-mail address _____

NMOC
JUL 31 2019
DISTRICT III