



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/13/19 Operator Enduring Resources API #30-0 39-24562
Property Name Rincon Unit Well No. 257 Location: Unit 16 Section 16 Township 27N Range 06W
Well Status (Shut-In or Producing) Initial PSI: Tubing 31 Intermediate N/A Casing 32 Bradenhead 11

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	BH	Int	Csg	Int	Csg	
TIME						
5 min	Ø		32			
10 min	Ø		32			
15 min	Ø		32			
20 min						
25 min						
30 min						

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		
Gas	✓	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 21

INTERMEDIATE N/A

REMARKS:

bradenhead blew down to nothing in approx 25 seconds.

By John D. Dettmer
HSE Tech
(Position)

Witness _____

E-mail address JDettmer@EnduringResources.com

NMOC
AUG 20 2019
DISTRICT III

8-19-19