

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/11/19 Operator_ENDURING RESOURCES IV LLC_API #30-039-24745____

Property Name_RINCON UNIT_Well No. 291 Location: Unit A Section 34 Township 27N Range 07W

Well Status(Shut-In or Producing) Initial PSI: Tubing 28 Intermediate M/A Casing 29 Bradenhead

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE					FLOW CHARACTERISTICS			
Testing	Bradenhe		INTE	RM		BRADENHEAD	INTERMEDIATE	
BH	Int) (Csg	Int	Csg				
TIME 5 min		29			Steady Flow			
10 min		29			Surges			
15 min		29			Down to Not	hing		_ /
20 min					Nothing			_
25 min					Gas		- VI	
30 min							NMOCI	
							JUL 15	2019
If bradenhead flowed water, check all of the description					tions that apply bel	<u>ow:</u>	DISTRICT	111
CLEA	AR	FRESH_		SALTY_	SULFUR	BLACK		
5 MINUTE SI REMARKS:	HUT-IN PF	RESSURI	£	BRADEN	HEAD	INTERMEDIAT	EN/A	
By John HSE Tee (Posi E-mail address	tion)			Erdua	Witness	5. Cita		7/15/19