

NEW MEXICO ENERGY, MUNERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test_7-15-19_ Operator: Enervest Operating, LLC API # 30-039-29937

Property Name: Jic. Cont. 155# Well No. & Location: Unit 29_Section: 29_Township: 26N Range: _____5W___

Well Status (Shut-In or Producing) Initial PSI: Tubing_105_Intermediate_ Casing_105_Braden head_0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

	PRESSURE					FLOW CHARACTERISTICS		
Testing		Brader	head	INTE		BRADEN	HEAD	INTERMEDIATE
TIME	BH	Int	Csg	Int	Csg			
5 min	0		105			Steady Flow		
10 min	0		105_			Surges		
15 min	_0		105			Down to Nothing		
20 min						Nothingx		
25 min						Gas		
30 min						Gas & Water		
						Water		
If braden	head	flowed	water, chec	k all of ti	ne descriptio	ns that apply below:	I	
(CLEAF	۲	FRESH_		SALTY	BLACK		
5 MINUT	TE SH	UT-IN	PRESSURI	2	BRADENH	AD_0 INTERM	IEDIAT	E
REMARK No Blov		ll has no	intermediat	e				
By Rodale Curley						Witness		
Lease Ope	erator_	E	2	2			tonitalitä la	MMOCD
(Positi	on)						
E-mail address								JUL 3 1 2019
							h	ISTRICT III