

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test_7-18-19_ Operator: **Enervest Operating, LLC** API # 30-039-31170

Property Name: Jicarilla B Well No. 3R Location: Unit J Section: 15 Township: 26N Range: 5W

Well Status (Shut-In or Producing) Initial PSI: Tubing_115_ Intermediate_ Casing_120_ Braden head_0_

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		120		
10 min	0		120		
15 min	0		120		
20 min					
25 min					
30 min					

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE	BRADENHEAD	0	INTERMEDIATE
---------------------------	------------	---	--------------

REMARKS:

No blow

By Rodale Curley

Witness _____

Lease Operator _____
(Position)

E-mail address

NMOC
JUL 31 2019
DISTRICT III