



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

NMOCD

AUG 07 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/1/19 Operator ENDURING RESOURCES IV LLC API #30-039-31236

Property Name: NE CHACO COM Well No: 256H Location: Unit M Section 18 Township 23N Range 06W

Well Status(Shut-In or Producing) Initial PSI: Tubing 46 Intermediate N/A Casing 168 Bradenhead 6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	Ø		161			
10 min	Ø		161			
15 min	Ø		171			
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø

INTERMEDIATE N/A

REMARKS:

blew down test after 10:26 am, 8/1/19
- bradenhead blew down to nothing in four seconds

By J. Dockter
HSE Tech
(Position)

Witness _____

E-mail address JDockter@EnduringResources.com

8/6/19