



**OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3ddistrict.htm](http://emnrd.state.nm.us/ocd/District%20III/3ddistrict.htm)**

NMOCB

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

07 2019

DISTRICT III

Date of Test 8/1/19 Operator ENDURING RESOURCES IV LLC API #30-039-31256

Property Name: NE CHACO COM Well No: 201H Location: Unit E Section 17 Township 23N Range 06W

Well Status(Shut-In or Producing) Initial PSI: Tubing 44 Intermediate N/A Casing 319 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME	Ø		324		
5 min	Ø		322		
10 min	Ø		325		
15 min	Ø				
20 min					
25 min					
30 min					

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		
Gas	✓	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD

INTERMEDIATE *N/A*

REMARKS:

- blew down, test after 9:20am, 8/1/19

- brackenhead had three second blow down to nothing

By Robert A. Kline

Witness

HSE Tech

(Position)

E-mail address JDockter@EngineeringResources.com

8/6/19