



OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.d.state.nm.us/ocd/District III/3distric.htm>

AUG 07 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/31/19 Operator ENDURING RESOURCES IV LLC API # 30-039-31294

Property Name: NE CHACO COM Well No: 243H Location: Unit L Section 16 Township 23N Range 06W

Well Status(Shut-In or Producing) Initial PSI: Tubing 47 Intermediate N/A Casing 155 Bradenhead <1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	BRADENHEAD			INTERMEDIATE		
	BH	Int	Csg	Int	Csg	
TIME	Ø		155			
5 min	Ø		153			
10 min	Ø		154			
15 min						
20 min						
25 min						
30 min						

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		
Gas	✓	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD

INTERMEDIATE *NA*

REMARKS:

REMARKS:

- 7/31/17 2:34pm, test after.
- braderhead blew down after 3 seconds.

By John Docter
HSE Tech
(Position)

Witness

E-mail address

E-mail address JDockter@EnduringResources.com

8/6/19