



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

NMOC

AUG 07 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/31/19 Operator ENDURING RESOURCES IV LLC API #30-039-31298

Property Name: NE CHACO COM Well No: 912H Location: Unit E Section 05 Township 23N Range 06W

Well Status(Shut-In or Producing) Initial PSI: Tubing 32 Intermediate N/A Casing 326 Bradenhead < 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			FLOW CHARACTERISTICS		
	Bradenhead BH	Int	Csg	Bradenhead	INTERMEDIATE	
5 min	<u>Ø</u>		<u>329</u>			Steady Flow
10 min	<u>Ø</u>		<u>339</u>			Surges
15 min	<u>Ø</u>		<u>338</u>			Down to Nothing <input checked="" type="checkbox"/>
20 min						Nothing <input checked="" type="checkbox"/>
25 min						Gas
30 min						Gas & Water
						Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø

INTERMEDIATE N/A

REMARKS:

Blew down, test in 24 hrs, after 1:26pm on 7/31/19
bradenhead blew down to nothing in three seconds

By J. Dockett
HSE Tech
(Position)

Witness _____

E-mail address JDockett@EnduringResources.com

8/6/19