NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3district.htm

NMOCD
AUG 07 2019
DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/31/19 Operator ENDURING RESOURCES IV LLC API #30-039-31299

Property Name: NE CHACO COM Well No: 902H Location: Unit E Section 05 Township 23N Range 06W

Well Status(Shut-In or Producing) Initial PSI: Tubing 30 Intermediate N/A Casing 235 Bradenhead <1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing TIME	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
5 min	Ø		239		
10 min	Ø		230		
15 min	Ø		227		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		
Gas	✓	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR____ FRESH____ SALTY____ SULFUR____ BLACK____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD Ø INTERMEDIATE N/A

REMARKS:
test after 24 hrs, on 7/31/19, 1:25pm
bradenhead blew down after three seconds

By John Dockter
HSE Tech
(Position)

Witness

E-mail address JDockter@enduringresources.com

8/6/19