



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 8/7/19 Operator ENDURING RESOURCES IV LLC API #30-043-21320

Property Name: S ESCAVADA UNIT Well No: 353H Location: Unit F Section 26 Township 22N Range 07W

Well Status(Shut-In or Producing) Initial PSI: Tubing 158 Intermediate N/A Casing 606 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead		INTERM			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	Ø		606			Steady Flow	
10 min	Ø		606			Surges	
15 min	Ø		606			Down to Nothing	
20 min						Nothing	
25 min						Gas	
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø INTERMEDIATE N/A

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By [Signature]  
HSE Tech  
(Position)

Witness \_\_\_\_\_

E-mail address JDockour@EnduringResources.com

NMOC  
AUG 14 2019  
DISTRICT III

8/13/19