



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

NMOCOD

AUG 20 2019

DISTRICT 111

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8.20.19 Operator Hilco Energy Co API #30-0 39-07444
Property Name SJ 28744 Well No. 55 Location: Unit 12 Section 12 Township 28 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 83 Intermediate 0 Casing 83 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	83	0	78
10 min	0	0	82	0	77
15 min	0	0	80	0	77
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

Location has 430 H- BH Nothing when opened.
Started flowing at 10 minutes Nothing when opened
after 5 min shut-in. Int. Nothing when opened. Nothing
By Alv 76 Witness Momca fueling when opened
after 5 min
Shut in

(Position)

E-mail address _____