



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

NMOC

AUG 20 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-20-19 Operator Hilcorp Energy API #30-0 39-20879
Property Name SS 28-7-14 Well No. 218 Location: Unit Section 12 Township 28 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 118 Intermediate 0 Casing 117 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	99	0	102
10 min	0	0	84	0	105
15 min	0	0	92	0	107
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD

INTERMEDIATE

REMARKS:

BH- light blow to dead at 4 seconds Casing started flowing at 2 minutes long puff when opened after 5 min shut in. Int- nothing when opened.
By Mike Scanlon Witness Monica Kuchling
(Position) When opened after 5 min shut in
E-mail address