



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6/25/19 Operator ENDURING RESOURCES IV LLC API #30-039-21719

Property Name RINCON UNIT Well No. 083A Location: Unit P Section 23 Township 27N Range 06W

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 46 Intermediate N/A Casing 61 Bradenhead <1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	<u>Ø</u>		<u>60</u>		
10 min	<u>Ø</u>		<u>60</u>		
15 min	<u>Ø</u>		<u>59</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	☒	
Nothing		
Gas	☒	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD Ø INTERMEDIATE N/A

REMARKS: bradenhead showed pressure of less than one psi
but blew down for approximately 45 seconds

By John Dockter

Witness _____

HSE Tech
(Position)

E-mail address JDockter@EnduringResources.com

DISTRICT III

7/9/19