



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 R/D BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://omnrd.state.nm.us/ocd/District III/district.htm](http://omnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/21/19 Operator Benson Montin Greer API #30-0 39-22592

Property Name EPCMU Well No. 40 Location: Unit E Section 19 Township 27N Range 1E

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 26 Bradenhead 4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>26</u>		
10 min	<u>0</u>		<u>26</u>		
15 min	<u>0</u>		<u>26</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	☒
Nothing	☒
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

Bradenhead Had 4 PSI Blew down in 38 seconds and
stayed at 0 PSI for Duration of Test

By Hevrie Velazquez
Lease operator
(Position)

Witness _____

E-mail address _____

MMDCD
SEP 05 2019
DISTRICT III