



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.d.state.nm.us/ocd/District III/district.htm](http://emnr.d.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/22/2019 Operator Benson Montino Greer API #30-0 39-23213

Property Name EPCmu Well No. 33 Location: Unit P Section 5 Township 26N Range 1E

Well Status (Shut-In or Producing) Initial PSI: Tubing 75 Intermediate N/A Casing 11 Bradenhead 14

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>1</u>		<u>11</u>		
10 min	<u>0</u>		<u>11</u>		
15 min	<u>0</u>		<u>11</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>✓</u>
Nothing	<u>✓</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 1 INTERMEDIATE

REMARKS: Bradenhead Had 14 PSI it Blew down in 2 min 15 seconds and
stayed a 0 PSI for Duration of Test

By Bernie Velazquez
Lease operator
(Position)

Witness

E-mail address

MOCD
SEP 05 2019
DISTRICT III