



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 8.29.19 Operator Hilcorp Energy API # 30-0 45-23779

Property Name Stanwood Gas Com SWD Well # 1 Location: Unit 2 Sec 17 Twn 32 Rge 12

Land Type:

State _____
Federal _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal ☒
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

NMOCD
AUG 30 2019
DISTRICT III

Temporarily Abandoned Well (Y/N): (N) TA Expires: _____

Casing Pres. 124
Bradenhead Pres. 0
Tubing Pres. 730
Int. Casing Pres. 0

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. 2400

Pressured annulus up to 570 psi. for 30 mins. Test passed/failed (N)

REMARKS:

Bled Casing to 0 - packer set 7004
(7) Def 7062

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

SWD Operator
(Position)

Revised 02-11-02