



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

NMOC

SEP 03 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

Date of Test 9.3.19 Operator Hilcorp Energy API #30-0 45.27935
Property Name San Juan SE 8 1/4 SW 1/4 Well No. 301 Location: Unit Section 16 Township 31 Range 8
Well Status (Shut-In or Producing) Initial PSI: Tubing 2171 Intermediate 0 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	0.4	0	0.4
10 min	0	0	0.4	0	0.4
15 min	0	0	0.4	0	0.4
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	✓
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD

INTERMEDIATE

REMARKS:

BH - nothing when opened. Nothing when
opened after 5 min shut in. Int. light blow to
dead at 19 seconds. Nothing when opened after
5 min shut in.

By Lester Whipple JWP Operator
(Position)

Witness Nomica Cukling

E-mail address