

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. Jicarilla Contact 120
2. Name of Operator LOGOS Operating, LLC		6. If Indian, Allottee or Tribe Name Jicarilla Apache
3a. Address 2010 Afton Place Farmington, NM 87401	3b. Phone No. (include area code) (505) 787-2218	7. Unit of CA/Agreement, Name and/or No.
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1850 FSL & 1000 FWL, NW/SW, L Sec 29 T26N R04W		8. Well Name and No. Jicarilla 120 C 004
		9. API Well No. 30-039-06291
		10. Field and Pool or Exploratory Area Blanco P.C. South (Prorated gas)
		11. Country or Parish, State Rio Arriba County, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	BH Remediation
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

LOGOS requests to perform a Bradenhead Remediation per the attached procedure and current wellbore diagram.

Notify NMOCD 24 hrs
prior to beginning
operations

NMOCD

SEP 11 2019

DISTRICT III

Notify the agencies if any casing repairs are
needed prior to the repair.

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Marie E. Florez		Regulatory Specialist
Signature <i>Marie E. Florez</i>		Date 08/30/2019

THE SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by	Title	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

NMOCD



2010 Afton Place
Farmington, NM 87401
Phone: (505) 278-8720
Fax: (505) 326-6112

Jicarilla 120 C 004

API 30-039-06291

Section 29 Township 26N Range 04W Unit Letter L

Bradenhead Remediation Plan of Action

1. Check secondary seal on wellhead and replace if testing indicates a failure.
2. If wellhead testing and repair is done, conduct a re-test of bradenhead.
3. If bradenhead gas is not eliminated by wellhead repair, set plug within 50' of top perforation and conduct MIT.
4. Evaluate bradenhead repair and shut off flow to the bradenhead by repair or plug if necessary.



Wellbore Schematic

Well Name: Jicarilla 120 C 004
Location: Sec 29, T26N, R04W 1850' FSL & 1000' FWL
County: Rio Arriba
API #: 30-039-06291
Co-ordinates: Lat: 36.455481 Long: -107.279774
Elevations: GROUND: 6785'
KB: 6795'
PBTD: 3439'
Depths (KB): TD: 3478'

Date Prepared: 3/31/2017
Last Updated: 7/23/2019 Dickens
Spud Date: 5/12/1957
Completion Date: 5/30/1957
Last Workover Date:

