Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5.	Lease Serial No.
	NMNM136161

SUNDRY Do not use thi abandoned wel	NMNM136161 6. If Indian, Allottee or Tribe Name EASTERN NAVAJO								
SUBMIT IN T	7. If Unit or CA/Agreement, Name and/or No. NMNM135219A								
Type of Well Oil Well	8. Well Name and No. BETONNIE TSOSIE UNIT 108H								
Name of Operator DJR OPERATING LLC	E FORD		9. API Well No. 30-045-35515-00-X1						
3a. Address 1600 BROADWAY SUITE 196 DENVER, CO 80202	60	. (include area code) 2-3476		10. Field and Pool or Exploratory Area BASIN MANCOS					
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description,			11. County or Parish, State					
Sec 11 T23N R8W SWSW 03- 36.235220 N Lat, 107.659374				SAN JUAN COUNTY, NM					
12. CHECK THE AF	PROPRIATE BOX(ES)	TO INDICA	TE NATURE OF	F NOTICE,	REPORT, OR OTH	HER I	DATA		
TYPE OF SUBMISSION	TYPE OF	ACTION							
☐ Notice of Intent	☐ Acidize	□ Deepen □		□ Product	duction (Start/Resume)		Water Shut-Off		
	☐ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclam	Reclamation		Well Integrity		
Subsequent Report	☐ Casing Repair	■ New Construction		☐ Recomp	ecomplete		Other illing Operations		
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon		_	orarity Abandon		ining Operations		
13. Describe Proposed or Completed Ope		Convert to Injection Plug Back Wat		□ Water I					
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Production Liner & Cement 7/18/19 Pressure Test 7 inch casing. 1500 psi 30 mins. Test Good recorded on Pason. Drill ahead 6-1/8 inch lateral. Tag cement Drill out 7 inch cement shoe track @ 5832 to 5903. Drill ahead to									
7/19/19 Drill ahead 7782 to 11 7/20/19 Drill ahead 11242 to N 7/21/19 ? 7/22/19 Run Liner 1 @ 5482, 1.50 ft. XO @ 5487,	MD 13675/TVD 5200 93 its 4.5 inch 11.6 lb P-1	acker TOL @ 5458, 5.29 ft. hanger			510	KU6 27 2			
ft., Type II collar @ 13647, 10. sleeve @ 13622, 10.02 ft. pup Landed on mandrel 40K & 35k	r @ 13659, 3.74 f	ft. Alpha	1.02		ODOWN				
release. Pressure test lines 55		ande	2 0° s						
14. I hereby certify that the foregoing is	Electronic Submission #4	ERATING LL	, sent to the Farn	nington					
Name (Printed/Typed) SHAW-MA	Title REGULA	ATORY SPI	ECIALIST						
Signature (Electronic S	Submission)	Date 07/31/20)19						
	THIS SPACE FO	R FEDERA	L OR STATE (OFFICE U	SE				
Approved By ACCEPT	JOE KILLIN TitlePETROLEI	NS UM ENGINI	EER		Date 08/27/2019				
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conductive the conductive transfer of the conductive t	Office Farmingt	on							
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s				willfully to ma	ake to any department or	agency	y of the United		

⁽Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Additional data for EC transaction #476075 that would not fit on the form

32. Additional remarks, continued

Cement 4.5 inch production liner 10 bbls FW & tuned 40 bbls 11.5 ppg spacer. Pump 190.3 bbls (786 sks) mixed @ 13.3 ppg, 1.36 yield, 3.00 gal/sk cement. Drop plug, displace with 172.5 bbls (10bbls FW w/ MMCR, followed by 120 bbls FW w/ biocide) @ 8.30 ppg. Bump plug @ 2600 psi, floats held. Set packer. Pressure test packer 5 mins @ 500 psi, pull out of hanger. Displace intermediate casing w/ FW (biocide). 25 bbls cement back to surface. Test to 5000 psi. Rig Release 7/23/19 00:00.