Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

BU	UREAU OF LAND MANA	GEMENT			Expires: January 31, 2018			
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					5. Lease Serial No. NMNM109385			
					6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. NMNM135367A			
Type of Well Gas Well □ Other					8. Well Name and No. VENADO CANYON UNIT 204H			
2. Name of Operator Contact: SHAW-MARIE FORD					9. API Well No.			
DJR OPĖRATING LLC	30-043-2129			0-00-X1				
3a. Address 1600 BROADWAY SUITE 196 DENVER, CO 80202	3b. Phone No. (include area code) Ph: 505-632-3476			10. Field and Pool or Exploratory Area BASIN MANCOS				
4. Location of Well (Footage, Sec., T.	11. County or P			rish, State				
Sec 12 T22N R6W NWSW 1335FSL 163FWL 36.148430 N Lat, 107.428795 W Lon				SANDOVAL COUNTY, NM		ΝM		
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICA	ΓΕ NATURE O	F NOTICE,	REPORT, OR OTH	HER DA	TA	
TYPE OF SUBMISSION	TYPE OF ACTION							
- National Character	☐ Acidize ☐		Deepen Prod		ion (Start/Resume)	☐ Wat	ter Shut-Off	
☐ Notice of Intent	☐ Alter Casing ☐ I		raulic Fracturing	☐ Reclamation		☐ Wel	☐ Well Integrity	
Subsequent Report	☐ Casing Repair ☐		Construction	□ Recomplete		⊘ Other		
☐ Final Abandonment Notice	☐ Change Plans	Change Plans		and Abandon		Drillin	Drilling Operations	
₽(☐ Convert to Injection	Convert to Injection		Back Water I				
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Well Spud on 8/28/19. Intermediate Casing & Cement 9/1/19: MIRU. NU 11-inch 5K BOP on pre-set 9.625-inch surface casing. Pressure test annular and TIW 250 psi low 5 min. 1500 psi high 10 min. Test blind rams, HCR, 4-inch pipe rams, kill valves, check valve, lower kelly, choke manifold & valves, full opening safety valve & the inside BOP valve: low 250 psi for 5 min. High 3000 psi for 10 min. Test 9.625-inch surface casing 1500 psi for 30 min. Test good. Drill ahead 8.75-inch to 612 ft. 9/2/19: Drill ahead 8.75-inch 612 ft to 4562 ft. TOH. 9/3/19: Wash & Ream 8.75-inch hole.								
9/4/19: Drill ahead 8.75-inch 4562 to 5680 ft. 9/5/19: RU casing crew. Run 135 its & 2 pups of 26# J55 LT&C 7-inch intermediate casing set at 567					5674		EP 23 2019	
MD 5339 TVD. Float collar at 5627 ft. Circulate and condition for cement. 3500 psi test on lines. Cement with Halliburton (40% excess on both Lead and Tail). 10 bbls FW spacer at 8.3# followed by								
14. I hereby certify that the foregoing is	Electronic Submission #4	ERATING LL	, sent to the Farr	mington				
Name (Printed/Typed) SHAW-MA	Title REGULATORY SPECIALIST							
Signature (Electronic S	Submission)		Date 09/18/20	019				
· · · · · · · · · · · · · · · · · · ·	THIS SPACE FO	R FEDERA			SE			
Approved By ACCEPTED			JOHN HOFFMAN TitlePETROLEUM ENGINEER		EER	D	ate 09/19/2019	
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu	Office Farmington							
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s				willfully to ma	ake to any department or	agency of	the United	

(Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Additional data for EC transaction #483795 that would not fit on the form

32. Additional remarks, continued

30 bbls tuned spacer at 11.5#. LEAD: 172.8 bbls (508 sx) at 12.3#, 1.9 yield, 10.36 gps. TAIL: 70.6 bbls (305 sx) at 13.5#, 1.3 yield, 5.81 gps. No cement returns to surface. Full returns were observed while pumping & displacing cement until 170 bbls into the 216 bbl displacement, with 10 bbls of the tuned spacer recovered. No additional returns were observed for the remaining 46 bbls of displacement. Bumped plug with 2300 psi. Checked floats. Floats held. Cementing company analyzed the lift pressures during the job & calculated top of cement at 90 ft. Volumetric calculations put the cement top at 700 ft. The Ojo Alamo formation top is at 1339 ft MD. 9/6/19 ? Install night cap. Skid Rig to 203H