



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://omnrud.state.nm.us/ocd/District15/33district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-19-19 Operator Domunion Prod API #30-0 31 05192

Property Name H6V 23 Well No. 23 Location: Unit D Section 1 Township 17 Range 9

Well Status (Shut-In) or Producing Initial PSI: Tubing Intermediate Casing open Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		0		
10 min	0		0		
15 min	0		0		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: nothing when opened BHT, nothing after 5 min
shut in.

By [Signature]
(Position)

Witness

E-mail address

NMOC
SEP 11 2019
DISTRICT III