

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test $8-11-19$ Ope	erator Dominion Prod	API #30-0_3 -	20596
Property Name_\(\mathfrak{HS}\) Well No	o. $\sqrt[6]{8}$ Location: Unit $\sqrt[8]{8}$ Se	ection 36 Townsh	nip <u>/</u> Range 9
Well Status (Shut-In or Producing) Tubing 1 Intermediate Casing 0 Bradenhead ()			
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH			
PRESSURES: TIME BRADENHEAD INTERMEDIATE C	CASING_	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes 0	Steady Flow		
10 minutes 0	Surges		
15 minutes O	Down to Nothing		
20 minutes	Nothing		
25 minutes	Gas	/	
30 minutes	Gas & Water		
	Water		
If bradenhead flowed water, check all of the descriptions that apply below:			OCD
CLEAR FRESH SALTY SULFUR BLACK \$EP 1 2019			
5 MINUTE SHUT-IN BRADENHEAD \(\partial \) INTERMEDIATE \(\) O ISTRICT \(\lambda \rightarrow \)			
REMARKS: Itad a puff when spened BH, puff after			
Smin Strut In.			
By Plas Inns	Witness		,
(Position)			
E-mail address			