

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9/4/19 Operator_ENDURING RESOURCES IV LLC_API #30-039-05938	
Property Name: LYDIA RENTZ Well No: 004 Location: Unit A Section 19 Township 25N Range 03W	
Well Status(Shut-In or roducing) Initial PSI: Tubing 48 Intermediate MA Casing 23 Bradenhead	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bhadenhead INTERM BH Int Csg Int Gsg TIME 5 min 233 1 10 min 236	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE Steady Flow Surges
15 min 238	Down to Nothing
20 min_	Nothing
25 min	Gas
30 min_	Gas & Water
l	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE MARKS:	
By John Witness Witness	
HSE Tech	
E-mail address Dorrero Englering Resources. com SEP 1 6 2019	