

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9/6/19 Operator_ENDURIN	IG RESOURCES IV LLCAPI #30-039-06024
Property Name: C W ROBERTS Well No: 001 Location: Unit D Section 18 Township 25N Range 03W	
Well Status(Shut-In or Producing) Initial PSI: Tubing 44 Intermediate MA Casing 90 Bradenhead Status	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg TIME O	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
5 min 9 9 9 1 15 min 9 9 9 1 15 min 9 9 9 1 15 min 9 9 9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Steady Flow Surges Down to Nothing
20 min 25 min 30	Nothing Gas Gas & Water Water Gas & Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFUR BLACK 5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE REMARKS:	
	NMOCD
By the Better Wi	## SEP 1.9 2019 ## STRICT III
(Position) E-mail address Dockster a Enduring	Resonres. con DEGEIVED