



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

NMOC

10 16 2019
DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10.16.19 Operator Cross Timbers API #30-0 39-23140
Property Name Reuter Well No. 321 E Location: Unit Section 15 Township 26 Range 6
Well Status(Shut-In or Producing) Initial PSI: Tubing 89 Intermediate Casing 99 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		102		
10 min	0		104		
15 min	0		105		
20 min	0		106		
25 min	0		107		
30 min	0		107		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Nothing when opened replaced all inside added casing inside outside of H plate Nothing when opened after 5 min shut in

By Jeff Wagoner
Production Foreman
(Position)

Witness Monica Kuehling

E-mail address jwagoner@ctfieldservices.com