



NEW MEXICO
N. HATHAWAY, 2101 N. 10TH ST. N. MEXICO CITY, NM 87102

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9/20/2019 Operator Blackhawk API #30-0 392-5764
Property Name Jic 459-19 Well No. 9 Location: Unit E Section 19 Township 30N Range 3W
Well Status (Shut-In or Producing) Initial PSI: Tubing 24 Intermediate Casing 71 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	BH	Bradenhead Int	Csg	Int	Csg	
TIME						
5 min	0		71			
10 min	0		71			
15 min	0		71			
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

BH had zero on gauge and nothing when opened.
Casing had 71 psi and held steady through out Test.
BH-zero psi after 5 min shut in - nothing else.

By Robert Talamante
Plant/lease operator
(Position)

Witness

E-mail address rtalamante@blackhawkenergycorp.com
NMOCB

OCT 07 2019
DISTRICT III