

NEW MEXICO ENERGY, MINERÁLS & NATURAL RESOLRCES DEPARTMENT

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test	8/29/19	Operator BlackHawk Energy	API #30-0 39-26863

Property Name Jicarilla 29-02-08 Well No. 3 Location: Unit B Section 8 Township 29N Range 2W

Well Status(Shut-In or Producing Initial PSI: Tubing 11 Intermediate N/A Casing 11 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE				FLOW CHARACTERISTICS					
Testing	Bradenhe	ad	INTERM	BR	ADENHEAD	INTERMEDIATE			
BH	Int C	sg	Int Csg						
TIME 0	1	11		Steady Flow					
10 min 0		11		Surges					
15 min_ 0	1	11		Down to Nothing_	X				
20 min				Nothing					
25 min	+			Gas	X				
30 min				Gas & Water					
				Water					
If bradenhead flowed water, check all of the descriptions that apply below:									
CLEA	AR	FRESH	SALTY	SULFURB	BLACK				
5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A									
REMARKS:									
Opened Bradenhead on 8/26/19 poofed to zero in 4 seconds. did not pressure back up.									
$() \qquad \qquad$									
By	m	AM	H W	itness					
Lease Operator (Position)									
(Posi	tion)				aze.	ב יכא איי דרייקיינייני א			
E-mail address dsnell@blackhawkenergycorp.com						NMOCD			
						STP 10 2 9 STRIET 111			
					D	STRIGT IN			