



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/20/19 Operator BlackHawk Energy API #30-0 39-30576

Property Name Jicarilla 29-02-26 Well No. 21 Location: Unit E Section 26 Township 29N Range 2W

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 9 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME	<u>0</u>		<u>9</u>		
5 min	<u>0</u>		<u>9</u>		
10 min	<u>0</u>		<u>9</u>		
15 min	<u>0</u>		<u>9</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

Opened Bradenhead valve 8/19/19 was 0, nothing on it.

By Donny Snell
Lease Operator
(Position)

Witness _____

E-mail address dsnell@blackhawkenergycorp.com

NMOC
SEP 10 2019
DISTRICT III