

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9/13/19 Operator_ENDU	RING RESOURCES IV LLCAPI #30-043-21219
76"	Location: Unit D Section 08 Township 22N Range 05W
Well Status(Shut-In or Producing) Initial PSI:	Tubing/47Intermediate//ACasing/2 Bradenhead
OPEN BRADENHEAD AND INTERMEDIAT	E TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
PRESSURE Testing Bradenhead INTERM BH In Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min /2	Steady Flow
10 min 0 /2	Surges
15 min 9 /3	Down to Nothing
20 min 6	Nothing
25 min 25	Gas
30 min	Gas & Water
V	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY	SULFUR BLACK
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE	
REMARKS:	NMOCD
	SEP 19 2013
By Mand Dette	Witness DISTRICT III
OHSE Tech	
(Position)	DEGETVE
E-mail address Deeleting Enduly A	Esousces, Com SEP 1 6 2019
	ا ا