



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

NMOCD

SEP 23 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9.20.19 Operator Enduring Res. API #30-0 45-30605
Property Name Blanco Well No. 4B Location: Unit 12 Township 27 Range 9
Well Status (Shut-In or Producing) Initial PSI: Tubing 3164 Intermediate 1/A Casing 389 Bradenhead 4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	<u>0</u>		<u>389</u>		
10 min	<u>0</u>		<u>389</u>		
15 min	<u>0</u>		<u>389</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges	<u>/</u>	
Down to Nothing	<u>/</u>	
Nothing		
Gas		
Gas & Water		
Water	<u>/</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1/A

REMARKS:

Surge to dead at 16 seconds. 1/2 cup water
Nothing after 5 min shut-in

By John Datto
HSE Tech
(Position)

Witness Mona Leiding

E-mail address JDatto@EnduringResources.com