



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnrd.state.nm.us/ocd/District III3district.htm](http://emnrd.state.nm.us/ocd/District%20III3district.htm)

DISTRICT III

SEP 11 2019

NMOC

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9.10.19 Operator Hilcorp Energy API #30-0 39-23501

Property Name SJ 30-6 44 Well No. 1124 Location: Unit 26 Section 30 Township 30 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 492 Intermediate 0 Casing 3 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	2	0	3
10 min	0	0	3	0	3
15 min	0	0	3	0	3
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow		
Surges		
Down to Nothing		/
Nothing	/	
Gas		/
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

BH Nothing when opened - Nothing when opened after 5 min shut-in - Int light blow to vapors at 43 seconds - to dead at 5 min - Vapors when opened after 5 min shut-in

By Aster W. Perkins
SWP Operator
(Position)

Witness

Monica Kuehling 5 min shut-in

E-mail address _____